

CPC COOPERATIVE PATENT CLASSIFICATION

F MECHANICAL ENGINEERING; LIGHTING; HEATING; WEAPONS; BLASTING (NOTE omitted)

ENGINES OR PUMPS

F03 MACHINES OR ENGINES FOR LIQUIDS; WIND, SPRING, OR WEIGHT MOTORS; PRODUCING MECHANICAL POWER OR A REACTIVE PROPULSIVE THRUST, NOT OTHERWISE PROVIDED FOR

F03D WIND MOTORS

NOTES

1. This subclass covers wind motors, i.e. mechanisms for converting the energy of wind into useful mechanical power, and the transmission of such power to its point of use.
2. This subclass does not cover electrical power generation or distribution aspects of wind-power plants, which are covered by section H, e.g. H02J or H02P.
3. In this subclass, the following terms or expressions are used with the meanings indicated:
 - "rotor" means the wind-engaging parts of the wind motor and the rotary member carrying them;
 - "rotation axis" means the axis of rotation of the rotor.

1/00 Wind motors with rotation axis substantially parallel to the air flow entering the rotor (controlling thereof F03D 7/02)

WARNING

Group [F03D 1/00](#) is impacted by reclassification into groups [F03D 1/101](#), [F03D 1/125](#), [F03D 1/141](#), [F03D 1/165](#), [F03D 1/181](#) and [F03D 1/188](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 1/02 . having a plurality of rotors
- 1/025 . . {coaxially arranged}
- 1/04 . having stationary wind-guiding means, e.g. with shrouds or channels ([F03D 9/35](#) takes precedence)

WARNING

Group [F03D 1/04](#) is impacted by reclassification into groups [F03D 1/041](#), [F03D 1/042](#), [F03D 1/044](#), [F03D 1/046](#), [F03D 1/048](#), [F03D 1/051](#) and [F03D 1/053](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 1/041 . . {Convergent inlets, i.e. the inlet section is greater than the rotor section ([F03D 1/044](#) takes precedence)}

WARNING

Group [F03D 1/041](#) is incomplete pending reclassification of documents from groups [F03D 1/04](#), [F05B 2240/123](#), [F05B 2240/1231](#), [F05B 2240/13](#) and [F05B 2250/5011](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 1/042 . . {Divergent outlets, e.g. diffusers or ejectors ([F03D 1/044](#) takes precedence)}

WARNING

Group [F03D 1/042](#) is incomplete pending reclassification of documents from groups [F03D 1/04](#) and [F05B 2240/13](#).

Groups [F03D 1/04](#), [F05B 2240/13](#) and [F03D 1/042](#) should be considered in order to perform a complete search.

- 1/044 . . {Convergent divergent structures, e.g. venturis}

WARNING

Group [F03D 1/044](#) is incomplete pending reclassification of documents from groups [F03D 1/04](#), [F05B 2240/133](#) and [F05B 2250/5012](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 1/046 . . {comprising additional flow modifying means, e.g. vanes or turbulators}

WARNING

Group [F03D 1/046](#) is incomplete pending reclassification of documents from groups [F03D 1/04](#), [F05B 2240/12](#), [F05B 2240/121](#) and [F05B 2240/122](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 1/048 . . . {for changing the flow direction, e.g. a horizontal inlet and a vertical outlet}

WARNING

Group [F03D 1/048](#) is incomplete pending reclassification of documents from groups [F03D 1/04](#), [F03D 9/35](#), [F03D 9/37](#), [F03D 9/39](#) and [F03D 9/41](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 1/051 . . {Multiple shrouds, e.g. in series or in parallel}

WARNING

Group [F03D 1/051](#) is incomplete pending reclassification of documents from groups [F03D 1/04](#) and [F05B 2240/124](#).

Groups [F03D 1/04](#), [F05B 2240/124](#) and [F03D 1/051](#) should be considered in order to perform a complete search.

- 1/053 . . {comprising controllable elements, e.g. inlet valves or shutters}

WARNING

Group [F03D 1/053](#) is incomplete pending reclassification of documents from group [F03D 1/04](#).

Groups [F03D 1/04](#) and [F03D 1/053](#) should be considered in order to perform a complete search.

- 1/06 . . Rotors

WARNING

Group [F03D 1/06](#) is incomplete pending reclassification of documents from group [F03D 1/0625](#).

Group [F03D 1/06](#) is also impacted by reclassification into groups [F03D 1/0602](#), [F03D 1/0606](#) and [F03D 1/0608](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 1/0601 . . {using the Magnus effect}

- 1/0602 . . {having rotating wind-guiding means, e.g. associated with the hub}

WARNING

Group [F03D 1/0602](#) is incomplete pending reclassification of documents from groups [F03D 1/06](#), [F03D 1/0608](#) and [F03D 1/0625](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 1/0606 . . . {Shrouds}

WARNING

Group [F03D 1/0606](#) is incomplete pending reclassification of documents from groups [F03D 1/06](#), [F03D 1/0625](#) and [F05B 2240/33](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 1/0608 . . {characterised by their aerodynamic shape}

WARNING

Group [F03D 1/0608](#) is incomplete pending reclassification of documents from groups [F03D 1/06](#) and [F03D 1/0625](#).

Group [F03D 1/0608](#) is also impacted by reclassification into group [F03D 1/0602](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 1/0625 . . . {of the whole rotor, i.e. form features of the rotor unit}
(Frozen)

WARNING

Group [F03D 1/0625](#) is no longer used for the classification of documents as of August 1, 2023.

The content of this group is being reclassified into groups [F03D 1/06](#), [F03D 1/0602](#), [F03D 1/0606](#) and [F03D 1/0608](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 1/0633 . . . {of the blades}

WARNING

Group [F03D 1/0633](#) is impacted by reclassification into groups [F03D 1/0642](#), [F03D 1/0643](#), [F03D 1/0645](#), [F03D 1/0647](#), [F03D 1/0648](#), [F03D 1/0649](#) and [F03D 1/06495](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 1/0641 {of the section profile of the blades, i.e. aerofoil profile}

WARNING

Group [F03D 1/0641](#) is incomplete pending reclassification of documents from group [F05B 2240/30](#).

Group [F03D 1/0641](#) is also impacted by reclassification into groups [F03D 1/0642](#), [F03D 1/0643](#), [F03D 1/0645](#), [F03D 1/0647](#), [F03D 1/0648](#), [F03D 1/0649](#) and [F03D 1/06495](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/0642 {of the blade tip region}

WARNING

Group [F03D 1/0642](#) is incomplete pending reclassification of documents from groups [F03D 1/0633](#), [F03D 1/0641](#), [F05B 2240/301](#) and [F05B 2240/307](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/0643 {of the leading edge region}

WARNING

Group [F03D 1/0643](#) is incomplete pending reclassification of documents from groups [F03D 1/0633](#), [F03D 1/0641](#), [F05B 2240/301](#) and [F05B 2240/303](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/0645 {of the trailing edge region}

WARNING

Group [F03D 1/0645](#) is incomplete pending reclassification of documents from groups [F03D 1/0633](#), [F03D 1/0641](#), [F05B 2240/301](#), [F05B 2240/304](#) and [F05B 2240/3042](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/0647 {of the root or transition region}

WARNING

Group [F03D 1/0647](#) is incomplete pending reclassification of documents from groups [F03D 1/0633](#), [F03D 1/0641](#) and [F05B 2240/301](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/0648 {of changeable form, e.g. comprising inflatable elements}

WARNING

Group [F03D 1/0648](#) is incomplete pending reclassification of documents from groups [F03D 1/0633](#), [F03D 1/0641](#), [F05B 2240/301](#), [F05B 2240/31](#), [F05B 2240/311](#), [F05B 2240/312](#), [F05B 2240/3121](#) and [F05B 2240/313](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/0649 {of the blade surfaces, e.g. roughened}

WARNING

Group [F03D 1/0649](#) is incomplete pending reclassification of documents from groups [F03D 1/0633](#), [F03D 1/0641](#), [F05B 2240/301](#), [F05B 2240/306](#), [F05B 2240/3062](#) and [F05B 2240/32](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/06495 {Aerodynamic elements attached to or formed with the blade, e.g. flaps, vortex generators or noise reducers}

WARNING

Group [F03D 1/06495](#) is incomplete pending reclassification of documents from groups [F03D 1/0633](#), [F03D 1/0641](#), [F03D 7/0232](#), [F05B 2240/301](#), [F05B 2240/305](#), [F05B 2240/3052](#), [F05B 2240/306](#) and [F05B 2240/3062](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/065 . . . {characterised by their construction elements ([F03D 13/10](#) takes precedence)}

WARNING

Group [F03D 1/065](#) is incomplete pending reclassification of documents from group [F03D 1/0658](#).

Groups [F03D 1/0658](#) and [F03D 1/065](#) should be considered in order to perform a complete search.

1/0658 . . . {Arrangements for fixing wind-engaging parts to a hub}

WARNING

Group [F03D 1/0658](#) is impacted by reclassification into groups [F03D 1/065](#), [F03D 1/066](#), [F03D 1/0662](#), [F03D 1/0664](#), [F03D 1/0667](#), [F03D 1/0669](#) and [F03D 1/0671](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/066 {Connection means therefor, e.g. bushings or adapters}

WARNING

Group [F03D 1/066](#) is incomplete pending reclassification of documents from groups [F03D 1/0658](#), [F05B 2260/30](#), [F05B 2260/301](#) and [F05B 2260/3011](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/0662 {using kinematic linkage, e.g. tilt (bearing arrangements, pitch bearings [F03D 80/70](#))}

WARNING

Group [F03D 1/0662](#) is incomplete pending reclassification of documents from groups [F03D 1/0658](#), [F05B 2260/50](#), [F05B 2260/502](#), [F05B 2260/503](#), [F05B 2260/5032](#), [F05B 2260/504](#), [F05B 2260/505](#), [F05B 2260/506](#) and [F05B 2260/507](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/0664 {Pitch arrangements (controlling blade pitch [F03D 7/0224](#))}

WARNING

Group [F03D 1/0664](#) is incomplete pending reclassification of documents from groups [F03D 1/0658](#), [F03D 7/0224](#), [F05B 2260/50](#), [F05B 2260/502](#), [F05B 2260/503](#), [F05B 2260/5032](#), [F05B 2260/504](#), [F05B 2260/505](#), [F05B 2260/506](#), [F05B 2260/507](#), [F05B 2260/70](#), [F05B 2260/75](#), [F05B 2260/76](#), [F05B 2260/77](#), [F05B 2260/78](#) and [F05B 2260/79](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/0667 {characterized by the actuator arrangements}

WARNING

Group [F03D 1/0667](#) is incomplete pending reclassification of documents from groups [F03D 1/0658](#), [F03D 7/0224](#), [F05B 2260/70](#), [F05B 2260/75](#), [F05B 2260/76](#), [F05B 2260/77](#), [F05B 2260/78](#), [F05B 2260/79](#), [F05B 2270/605](#) and [F05B 2270/606](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/0669 {Hydraulic actuators}

WARNING

Group [F03D 1/0669](#) is incomplete pending reclassification of documents from groups [F03D 1/0658](#), [F03D 7/0224](#), [F05B 2260/76](#), [F05B 2260/79](#) and [F05B 2270/604](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/0671 {Electric actuators, e.g. motors}

WARNING

Group [F03D 1/0671](#) is incomplete pending reclassification of documents from groups [F03D 1/0658](#), [F03D 7/0224](#), [F05B 2260/76](#), [F05B 2260/79](#) and [F05B 2270/602](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/0675 . . . {of the blades}

WARNING

Group [F03D 1/0675](#) is impacted by reclassification into groups [F03D 1/0677](#), [F03D 1/0679](#), [F03D 1/0681](#), [F03D 1/0682](#), [F03D 1/0684](#), [F03D 1/0685](#), [F03D 1/0687](#), [F03D 1/0688](#), [F03D 1/069](#) and [F03D 80/301](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/0677 {Longitudinally segmented blades; Connectors therefor}

WARNING

Group [F03D 1/0677](#) is incomplete pending reclassification of documents from groups [F03D 1/0675](#) and [F05B 2240/302](#).

Groups [F03D 1/0675](#), [F05B 2240/302](#) and [F03D 1/0677](#) should be considered in order to perform a complete search.

1/0679 {Load carrying structures, e.g. beams}

WARNING

Groups [F03D 1/0679](#), [F03D 1/0681](#), [F03D 1/0682](#) and [F03D 1/0684](#) are incomplete pending reclassification of documents from groups [F03D 1/0675](#) and [F05B 2280/702](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/0681 {Spar caps}

1/0682 {incorporated into the shell structure}

1/0684 {Shear webs}

1/0685 {Actuation arrangements for elements attached to or incorporated with the blade (controlling flaps or slats [F03D 7/0232](#))}

WARNING

Group [F03D 1/0685](#) is incomplete pending reclassification of documents from groups [F03D 1/0675](#), [F03D 7/0232](#), [F05B 2240/30](#), [F05B 2240/305](#) and [F05B 2240/3052](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/0687 {of the blade tip region}

WARNING

Group [F03D 1/0687](#) is incomplete pending reclassification of documents from groups [F03D 1/0675](#) and [F05B 2240/307](#).

Groups [F03D 1/0675](#), [F05B 2240/307](#) and [F03D 1/0687](#) should be considered in order to perform a complete search.

1/0688 {of the leading edge region, e.g. reinforcements}

WARNING

Group [F03D 1/0688](#) is incomplete pending reclassification of documents from group [F03D 1/0675](#).

Groups [F03D 1/0675](#) and [F03D 1/0688](#) should be considered in order to perform a complete search.

1/069 {of the trailing edge region}

WARNING

Group [F03D 1/069](#) is incomplete pending reclassification of documents from group [F03D 1/0675](#).

Groups [F03D 1/0675](#) and [F03D 1/069](#) should be considered in order to perform a complete search.

1/0691 . . . {of the hub}

1/101 . {Nacelles (arrangement of components within nacelles [F03D 80/80](#))}

WARNING

Groups [F03D 1/101](#), [F03D 1/125](#), [F03D 1/141](#), [F03D 1/165](#) and [F03D 1/188](#) are incomplete pending reclassification of documents from groups [F03D 1/00](#), [F05B 2240/14](#) and [F05B 2240/142](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/125 . . {Access thereto, e.g. doors or platforms}

1/141 . . {Supporting structures, i.e. load carrying structures}

1/165 . . {Fairings, i.e. elements defining or supporting the outer surface}

1/181 . . {characterised by the connection to the tower, e.g. yaw systems (controlling the orientation in relation to wind direction [F03D 7/0204](#))}

WARNING

Group [F03D 1/181](#) is incomplete pending reclassification of documents from groups [F03D 1/00](#), [F03D 7/0204](#), [F05B 2240/14](#) and [F05B 2240/142](#).

All groups listed in this Warning should be considered in order to perform a complete search.

1/188 . . {made of several pieces and assembled on-site (assembly of wind motors [F03D 13/10](#))}

3/00 Wind motors with rotation axis substantially perpendicular to the air flow entering the rotor (controlling thereof [F03D 7/06](#))

3/002 . {the axis being horizontal}

3/005 . {the axis being vertical}

WARNING

Group [F03D 3/005](#) is impacted by reclassification into groups [F03D 3/009](#) and [F03D 3/011](#).

Groups [F03D 3/005](#), [F03D 3/009](#) and [F03D 3/011](#) should be considered in order to perform a complete search.

3/007 . . {using the Magnus effect}

3/009 . . {of the drag type, e.g. Savonius}

WARNING

Group [F03D 3/009](#) is incomplete pending reclassification of documents from groups [F03D 3/005](#), [F05B 2240/213](#), [F05B 2240/215](#) and [F05B 2240/216](#).

All groups listed in this Warning should be considered in order to perform a complete search.

3/011 . . {of the lift type, e.g. Darrieus or Musgrove}

WARNING

Group [F03D 3/011](#) is incomplete pending reclassification of documents from groups [F03D 3/005](#), [F05B 2240/212](#) and [F05B 2240/214](#).

All groups listed in this Warning should be considered in order to perform a complete search.

3/02 . . having a plurality of rotors

3/04 . . having stationary wind-guiding means, e.g. with shrouds or channels ([F03D 9/35](#) takes precedence)

3/0409 . . {surrounding the rotor ([F03D 3/0427](#) takes precedence)}

3/0418 . . . {comprising controllable elements}

3/0427 . . {with converging inlets, i.e. the guiding means intercepting an area greater than the effective rotor area ([F03D 3/0463](#), [F03D 3/049](#) take precedence)}

3/0436 . . {for shielding one side of the rotor}

3/0445 . . . {the shield being fixed with respect to the wind motor}

3/0454 {and only with concentrating action, i.e. only increasing the airflow speed into the rotor, e.g. divergent outlets ([F03D 3/0463](#) takes precedence)}

3/0463 {with converging inlets, i.e. the shield intercepting an area greater than the effective rotor area}

3/0472 . . . {the shield orientation being adaptable to the wind motor}

3/0481 {and only with concentrating action, i.e. only increasing the airflow speed into the rotor, e.g. divergent outlets ([F03D 3/049](#) takes precedence)}

3/049 {with converging inlets, i.e. the shield intercepting an area greater than the effective rotor area}

- 3/06 . Rotors
- 3/061 . . {characterised by their aerodynamic shape, e.g. aerofoil profiles}
- 3/062 . . {characterised by their construction elements}

WARNING

Group [F03D 3/062](#) is impacted by reclassification into groups [F03D 3/063](#) and [F03D 3/066](#).

Groups [F03D 3/062](#), [F03D 3/063](#) and [F03D 3/066](#) should be considered in order to perform a complete search.

- 3/063 . . . {Telescoping or folding wind engaging parts}

WARNING

Group [F03D 3/063](#) is incomplete pending reclassification of documents from groups [F03D 3/062](#) and [F05B 2240/2021](#).

Groups [F03D 3/062](#), [F05B 2240/2021](#) and [F03D 3/063](#) should be considered in order to perform a complete search.

- 3/064 . . . {Fixing wind engaging parts to rest of rotor}
- 3/066 . . . {the wind engaging parts being movable relative to the rotor}

WARNING

Group [F03D 3/066](#) is incomplete pending reclassification of documents from groups [F03D 3/062](#), [F03D 3/068](#) and [F05B 2240/218](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 3/067 {Cyclic movements}

WARNING

Group [F03D 3/067](#) is incomplete pending reclassification of documents from groups [F03D 3/068](#) and [F05B 2240/218](#).

Groups [F03D 3/068](#), [F05B 2240/218](#) and [F03D 3/067](#) should be considered in order to perform a complete search.

- 3/068 {mechanically controlled by the rotor structure}

WARNING

Group [F03D 3/068](#) is incomplete pending reclassification of documents from group [F05B 2240/218](#).

Group [F03D 3/068](#) is also impacted by reclassification into groups [F03D 3/066](#) and [F03D 3/067](#).

All groups listed in this Warning should be considered in order to perform a complete search.

5/00 Other wind motors (controlling thereof [F03D 7/00](#))**WARNING**

Group [F03D 5/00](#) is impacted by reclassification into groups [F03D 5/015](#), [F03D 9/322](#) and [F03D 9/324](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 5/005 . {Wind motors having a single vane which axis generate a conus or like surface}
- 5/015 . {of the tethered aircraft type, e.g. kites, with traction and retraction of the tether (controlling thereof [F03D 7/051](#))}

WARNING

Group [F03D 5/015](#) is incomplete pending reclassification of documents from groups [F03D 5/00](#) and [F05B 2240/9172](#).

Groups [F03D 5/00](#), [F05B 2240/9172](#) and [F03D 5/015](#) should be considered in order to perform a complete search.

- 5/02 . the wind-engaging parts being attached to endless chains or the like
- 5/04 . the wind-engaging parts being attached to carriages running on tracks or the like
- 5/06 . the wind-engaging parts swinging to-and-fro and not rotating

- 7/00 **Controlling wind motors (supplying or distributing electrical power [H02J](#), e.g. arrangements for adjusting, eliminating or compensating reactive power in networks [H02J 3/18](#); controlling electric generators [H02P](#), e.g. arrangements for controlling electric generators for the purpose of obtaining a desired output [H02P 9/00](#))**

WARNING

Group [F03D 7/00](#) is impacted by reclassification into group [F03D 7/051](#).

Groups [F03D 7/00](#) and [F03D 7/051](#) should be considered in order to perform a complete search.

- 7/02 . the wind motors having rotation axis substantially parallel to the air flow entering the rotor

WARNING

Group [F03D 7/02](#) is impacted by reclassification into group [F03D 7/0202](#).

Groups [F03D 7/02](#) and [F03D 7/0202](#) should be considered in order to perform a complete search.

- 7/0202 . . {controlling floating wind motors}

WARNING

Group [F03D 7/0202](#) is incomplete pending reclassification of documents from groups [F03D 7/02](#), [F03D 7/0204](#), [F03D 7/0224](#), [F03D 7/0236](#), [F05B 2240/93](#), [F05B 2240/931](#), [F05B 2240/932](#) and [F05B 2270/18](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 7/0204 . . . {for orientation in relation to wind direction}

WARNING

Group [F03D 7/0204](#) is impacted by reclassification into groups [F03D 7/0202](#) and [F03D 1/181](#).

Groups [F03D 7/0204](#), [F03D 7/0202](#) and [F03D 1/181](#) should be considered in order to perform a complete search.

- 7/0208 . . . {Orientating out of wind}
 7/0212 . . . {the rotating axis remaining horizontal}
 7/0216 . . . {the rotating axis changing to vertical position}
 7/022 . . {Adjusting aerodynamic properties of the blades}
 7/0224 . . . {Adjusting blade pitch}

WARNING

Group [F03D 7/0224](#) is impacted by reclassification into groups [F03D 1/0664](#), [F03D 1/0667](#), [F03D 1/0669](#), [F03D 1/0671](#), [F03D 7/0202](#), [F03D 17/029](#) and [F03D 80/701](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 7/0228 {of the blade tips only}
 7/0232 . . . {with flaps or slats (with aerodynamic drag devices on the blades for braking [F03D 7/0252](#))}

WARNING

Group [F03D 7/0232](#) is impacted by reclassification into groups [F03D 1/06495](#) and [F03D 1/0685](#).

Groups [F03D 7/0232](#), [F03D 1/06495](#) and [F03D 1/0685](#) should be considered in order to perform a complete search.

- 7/0236 . . . {by changing the active surface of the wind engaging parts, e.g. reefing or furling}

WARNING

Group [F03D 7/0236](#) is impacted by reclassification into groups [F03D 7/0202](#), [F03D 7/0237](#) and [F03D 7/0239](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 7/0237 {by means of telescoping blades}

WARNING

Group [F03D 7/0237](#) is incomplete pending reclassification of documents from groups [F03D 7/0236](#) and [F05B 2240/2021](#).

Groups [F03D 7/0236](#), [F05B 2240/2021](#) and [F03D 7/0237](#) should be considered in order to perform a complete search.

- 7/0239 {by means of teetering or coning blades}

WARNING

Group [F03D 7/0239](#) is incomplete pending reclassification of documents from groups [F03D 7/0236](#) and [F05B 2240/2022](#).

Groups [F03D 7/0236](#), [F05B 2240/2022](#) and [F03D 7/0239](#) should be considered in order to perform a complete search.

- 7/024 . . . {of individual blades}
 7/0244 . . {for braking}
 7/0248 . . . {by mechanical means acting on the power train}
 7/0252 . . . {with aerodynamic drag devices on the blades}
 7/0256 . . {Stall control (adjusting the blades in stall position [F03D 7/0224](#))}
 7/026 . . {for starting-up}
 7/0264 . . {for stopping; controlling in emergency situations (orientating out of wind [F03D 7/0208](#))}
 7/0268 . . . {Parking or storm protection}
 7/0272 . . {by measures acting on the electrical generator}
 7/0276 . . {controlling rotor speed, e.g. variable speed}
 7/028 . . {controlling wind motor output power}

WARNING

Group [F03D 7/028](#) is incomplete pending reclassification of documents from group [F03D 7/0288](#).

Groups [F03D 7/0288](#) and [F03D 7/028](#) should be considered in order to perform a complete search.

- 7/0284 . . . {in relation to the state of the electric grid}
 7/0288 . . . {in relation to clearance between the blade and the tower, i.e. preventing tower strike}

WARNING

Group [F03D 7/0288](#) is impacted by reclassification into group [F03D 7/028](#).

Groups [F03D 7/0288](#) and [F03D 7/028](#) should be considered in order to perform a complete search.

- 7/0292 . . . {to reduce fatigue}
 7/0296 . . {to prevent, counteract or reduce noise emissions}

WARNING

Group [F03D 7/0296](#) is incomplete pending reclassification of documents from group [F05B 2270/333](#).

Group [F03D 7/0296](#) is also impacted by reclassification into groups [F03D 7/0298](#), [F03D 7/0302](#), [F03D 17/015](#), [F03D 17/016](#) and [F03D 17/017](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 7/0298 . . . {to prevent, counteract or reduce vibrations}

WARNING

Groups [F03D 7/0298](#) and [F03D 7/0302](#) are incomplete pending reclassification of documents from groups [F03D 7/0296](#) and [F05B 2270/334](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 7/0302 . . . {of the tower}
 7/04 . . Automatic control; Regulation
 7/041 . . . {by means of a mechanical governor}
 7/042 . . . {by means of an electrical or electronic controller}
 7/043 {characterised by the type of control logic}
 7/044 {with PID control}
 7/045 {with model-based controls}
 7/046 {with learning or adaptive control, e.g. self-tuning, fuzzy logic or neural network}
 7/047 {characterised by the controller architecture, e.g. multiple processors or data communications}
 7/048 {controlling wind farms}

WARNING

Group [F03D 7/048](#) is impacted by reclassification into group [F03D 7/049](#).

Groups [F03D 7/048](#) and [F03D 7/049](#) should be considered in order to perform a complete search.

- 7/049 {in relation to the wake effect}

WARNING

Group [F03D 7/049](#) is incomplete pending reclassification of documents from groups [F03D 7/048](#) and [F05B 2270/204](#).

Groups [F03D 7/048](#), [F05B 2270/204](#) and [F03D 7/049](#) should be considered in order to perform a complete search.

- 7/051 . {the wind motors being supported in air by airborne structures; of the tethered aircraft type}

WARNING

Group [F03D 7/051](#) is incomplete pending reclassification of documents from groups [F03D 7/00](#) and [F05B 2270/18](#).

Groups [F03D 7/00](#), [F05B 2270/18](#) and [F03D 7/051](#) should be considered in order to perform a complete search.

- 7/06 . the wind motors having rotation axis substantially perpendicular to the air flow entering the rotor

WARNING

Group [F03D 7/06](#) is impacted by reclassification into group [F03D 7/065](#).

Groups [F03D 7/06](#) and [F03D 7/065](#) should be considered in order to perform a complete search.

- 7/065 . . . {controlling rotor speed}

WARNING

Group [F03D 7/065](#) is incomplete pending reclassification of documents from groups [F03D 7/06](#), [F05B 2270/101](#), [F05B 2270/1011](#), [F05B 2270/1012](#) and [F05B 2270/1014](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 9/00 **Adaptations of wind motors for special use; Combinations of wind motors with apparatus driven thereby; Wind motors specially adapted for installation in particular locations (hybrid wind-photovoltaic energy systems for the generation of electric power [H02S 10/12](#))**

- 9/007 . {the wind motor being combined with means for converting solar radiation into useful energy}
 9/008 . {the wind motor being combined with water energy converters, e.g. a water turbine}
 9/10 . Combinations of wind motors with apparatus storing energy
 9/11 . . storing electrical energy
 9/12 . . storing kinetic energy, e.g. using flywheels
 9/13 . . storing gravitational potential energy
 9/14 . . . using liquids
 9/16 . . . using weights
 9/17 . . storing energy in pressurised fluids
 9/18 . . storing heat
 9/19 . . storing chemical energy, e.g. using electrolysis
 9/20 . Wind motors characterised by the driven apparatus ([F03D 9/10 takes precedence](#))
 9/22 . . the apparatus producing heat
 9/25 . . the apparatus being an electrical generator ([F03D 9/22 takes precedence](#))

WARNING

Group [F03D 9/25](#) is impacted by reclassification into groups [F03D 15/205](#) and [F03D 15/207](#).

Groups [F03D 9/25](#), [F03D 15/205](#) and [F03D 15/207](#) should be considered in order to perform a complete search.

- 9/255 . . . {connected to electrical distribution networks; Arrangements therefor}
 9/257 {the wind motor being part of a wind farm}
 9/28 . . the apparatus being a pump or a compressor
 9/30 . Wind motors specially adapted for installation in particular locations (means for mounting or supporting wind motors [F03D 13/20](#))

WARNING

Group [F03D 9/30](#) is impacted by reclassification into groups [F03D 9/322](#) and [F03D 9/324](#).

Groups [F03D 9/30](#), [F03D 9/322](#) and [F03D 9/324](#) should be considered in order to perform a complete search.

- 9/32 . . . on moving objects, e.g. vehicles

WARNING

Group [F03D 9/32](#) is impacted by reclassification into groups [F03D 9/322](#) and [F03D 9/324](#).

Groups [F03D 9/32](#), [F03D 9/322](#) and [F03D 9/324](#) should be considered in order to perform a complete search.

- 9/322 . . . {the wind motors being supported in air by airborne structures, e.g. by kites (controlling thereof [F03D 7/051](#))}

WARNING

Group [F03D 9/322](#) is incomplete pending reclassification of documents from groups [F03D 5/00](#), [F03D 9/30](#), [F03D 9/32](#), [F05B 2240/917](#), [F05B 2240/9176](#), [F05B 2240/92](#), [F05B 2240/921](#), [F05B 2240/922](#) and [F05B 2240/923](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 9/324 {following a flying pattern}

WARNING

Group [F03D 9/324](#) is incomplete pending reclassification of documents from groups [F03D 5/00](#), [F03D 9/30](#), [F03D 9/32](#) and [F05B 2240/9174](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 9/34 . . . on stationary objects or on stationary man-made structures

- 9/35 . . . within towers, e.g. using chimney effects

WARNING

Group [F03D 9/35](#) is impacted by reclassification into group [F03D 1/048](#).

Groups [F03D 9/35](#) and [F03D 1/048](#) should be considered in order to perform a complete search.

- 9/37 with means for enhancing the air flow within the tower, e.g. by heating

WARNING

Group [F03D 9/37](#) is impacted by reclassification into group [F03D 1/048](#).

Groups [F03D 9/37](#) and [F03D 1/048](#) should be considered in order to perform a complete search.

- 9/39 by circulation or vortex formation

WARNING

Group [F03D 9/39](#) is impacted by reclassification into group [F03D 1/048](#).

Groups [F03D 9/39](#) and [F03D 1/048](#) should be considered in order to perform a complete search.

- 9/41 by using the wind outside the tower, e.g. using ejectors

WARNING

Group [F03D 9/41](#) is impacted by reclassification into group [F03D 1/048](#).

Groups [F03D 9/41](#) and [F03D 1/048](#) should be considered in order to perform a complete search.

- 9/43 . . . using infrastructure primarily used for other purposes, e.g. masts for overhead railway power lines

- 9/45 Building formations

- 9/46 Tunnels or streets

- 9/48 . . using landscape topography, e.g. valleys

13/00 Assembly, mounting or commissioning of wind motors; Arrangements specially adapted for transporting wind motor components

- 13/10 . Assembly of wind motors; Arrangements for erecting wind motors

WARNING

Group [F03D 13/10](#) is impacted by reclassification into groups [F03D 13/104](#), [F03D 13/108](#), [F03D 13/112](#), [F03D 13/116](#), [F03D 13/122](#), [F03D 13/126](#), [F03D 13/135](#) and [F03D 13/139](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 13/104 . . {Rotor installation, e.g. installation of blades}

WARNING

Group [F03D 13/104](#) is incomplete pending reclassification of documents from group [F03D 13/10](#).

Groups [F03D 13/10](#) and [F03D 13/104](#) should be considered in order to perform a complete search.

- 13/108 . . . {Alignment, e.g. of blades to rotor hub}

WARNING

Group [F03D 13/108](#) is incomplete pending reclassification of documents from groups [F03D 13/10](#) and [F05B 2230/604](#).

Groups [F03D 13/10](#), [F05B 2230/604](#) and [F03D 13/108](#) should be considered in order to perform a complete search.

- 13/112 . . {of towers; of masts}

WARNING

Group [F03D 13/112](#) is incomplete pending reclassification of documents from group [F03D 13/10](#).

Groups [F03D 13/10](#) and [F03D 13/112](#) should be considered in order to perform a complete search.

- 13/116 . . {of nacelles}

WARNING

Group [F03D 13/116](#) is incomplete pending reclassification of documents from group [F03D 13/10](#).

Groups [F03D 13/10](#) and [F03D 13/116](#) should be considered in order to perform a complete search.

- 13/122 . . {of auxiliary arrangements inside tower or nacelle, e.g. generators or transmission}

WARNING

Group [F03D 13/122](#) is incomplete pending reclassification of documents from group [F03D 13/10](#).

Groups [F03D 13/10](#) and [F03D 13/122](#) should be considered in order to perform a complete search.

- 13/126 . . {Offshore}

WARNING

Group [F03D 13/126](#) is incomplete pending reclassification of documents from group [F03D 13/10](#).

Groups [F03D 13/10](#) and [F03D 13/126](#) should be considered in order to perform a complete search.

- 13/135 . . {Pre-assembling, i.e. partially or completely assembling the wind motor before transport to the installation site}

WARNING

Group [F03D 13/135](#) is incomplete pending reclassification of documents from group [F03D 13/10](#).

Groups [F03D 13/10](#) and [F03D 13/135](#) should be considered in order to perform a complete search.

- 13/139 . . {Assembling or erecting wind motors by using lifting means}

WARNING

Group [F03D 13/139](#) is incomplete pending reclassification of documents from groups [F03D 13/10](#), [F05B 2230/61](#) and [F05B 2230/6102](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 13/20 . Arrangements for mounting or supporting wind motors; Masts or towers for wind motors

WARNING

Group [F03D 13/20](#) is incomplete pending reclassification of documents from group [F03D 13/22](#).

Group [F03D 13/20](#) is also impacted by reclassification into groups [F03D 13/2005](#), [F03D 13/201](#), [F03D 13/202](#), [F03D 13/203](#), [F03D 13/204](#), [F03D 13/205](#) and [F03D 13/206](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 13/2005 . . {Masts or poles}

WARNING

Group [F03D 13/2005](#) is incomplete pending reclassification of documents from groups [F03D 13/20](#), [F03D 80/00](#) and [F05B 2240/913](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 13/201 . . {Towers}

WARNING

Groups [F03D 13/201](#) and [F03D 13/202](#) are incomplete pending reclassification of documents from groups [F03D 13/20](#), [F03D 80/00](#) and [F05B 2240/912](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 13/202 . . . {Access thereto}

- 13/203 . . . {Lattice truss}

WARNING

Group [F03D 13/203](#) is incomplete pending reclassification of documents from groups [F03D 13/20](#), [F03D 80/00](#) and [F05B 2240/9121](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 13/204 . . . {Circumferentially segmented}

WARNING

Group [F03D 13/204](#) is incomplete pending reclassification of documents from groups [F03D 13/20](#) and [F03D 80/00](#).

Groups [F03D 13/20](#), [F03D 80/00](#) and [F03D 13/204](#) should be considered in order to perform a complete search.

- 13/205 . . . {Connection means, e.g. joints between segments}
- WARNING**
- Groups [F03D 13/205](#) and [F03D 13/206](#) are incomplete pending reclassification of documents from groups [F03D 13/20](#), [F03D 13/22](#) and [F03D 80/00](#).
- All groups listed in this Warning should be considered in order to perform a complete search.
- 13/206 {between the tower and the foundation}
- 13/22 . . {Foundations specially adapted for wind motors} (Frozen)
- WARNING**
- Group [F03D 13/22](#) is no longer used for the classification of documents as of August 1, 2023.
- The content of this group is being reclassified into groups [F03D 13/20](#), [F03D 13/205](#), [F03D 13/206](#) and [F03D 13/256](#).
- All groups listed in this Warning should be considered in order to perform a complete search.
- 13/25 . . specially adapted for offshore installation
- WARNING**
- Group [F03D 13/25](#) is impacted by reclassification into group [F03D 13/256](#).
- Groups [F03D 13/25](#) and [F03D 13/256](#) should be considered in order to perform a complete search.
- 13/256 . . . {on a floating support, i.e. floating wind motors}
- WARNING**
- Group [F03D 13/256](#) is incomplete pending reclassification of documents from groups [F03D 13/22](#), [F03D 13/25](#), [F05B 2240/93](#), [F05B 2240/931](#) and [F05B 2240/932](#).
- All groups listed in this Warning should be considered in order to perform a complete search.
- 13/30 . Commissioning, e.g. inspection, testing or final adjustment before releasing for production
- WARNING**
- Group [F03D 13/30](#) is impacted by reclassification into groups [F03D 80/002](#) and [F03D 80/011](#).
- Groups [F03D 13/30](#), [F03D 80/002](#) and [F03D 80/011](#) should be considered in order to perform a complete search.
- 13/35 . . Balancing static or dynamic imbalances

- 13/40 . Arrangements or methods specially adapted for transporting wind motor components
- WARNING**
- Group [F03D 13/40](#) is impacted by reclassification into groups [F03D 13/401](#), [F03D 13/402](#) and [F03D 13/403](#).
- All groups listed in this Warning should be considered in order to perform a complete search.
- 13/401 . . {for transporting or storing blades}
- WARNING**
- Group [F03D 13/401](#) is incomplete pending reclassification of documents from group [F03D 13/40](#).
- Groups [F03D 13/40](#) and [F03D 13/401](#) should be considered in order to perform a complete search.
- 13/402 . . {for transporting or storing towers}
- WARNING**
- Group [F03D 13/402](#) is incomplete pending reclassification of documents from group [F03D 13/40](#).
- Groups [F03D 13/40](#) and [F03D 13/402](#) should be considered in order to perform a complete search.
- 13/403 . . {for transporting or storing nacelles}
- WARNING**
- Group [F03D 13/403](#) is incomplete pending reclassification of documents from group [F03D 13/40](#).
- Groups [F03D 13/40](#) and [F03D 13/403](#) should be considered in order to perform a complete search.
- 15/00 **Transmission of mechanical power**
- WARNING**
- Group [F03D 15/00](#) is impacted by reclassification into groups [F03D 15/10](#), [F03D 15/101](#), [F03D 15/201](#), [F03D 15/202](#), [F03D 15/205](#) and [F03D 15/207](#).
- All groups listed in this Warning should be considered in order to perform a complete search.
- 15/05 . {using hollow exhausting blades}
- 15/10 . using gearing not limited to rotary motion, e.g. with oscillating or reciprocating members
- WARNING**
- Group [F03D 15/10](#) is incomplete pending reclassification of documents from group [F03D 15/00](#).
- Group [F03D 15/10](#) is also impacted by reclassification into groups [F03D 15/101](#), [F03D 80/701](#), [F03D 80/703](#), [F03D 80/705](#), [F03D 80/707](#) and [F03D 80/709](#).
- All groups listed in this Warning should be considered in order to perform a complete search.

- 15/101 . . {of the epicyclic or planetary type}
- WARNING**
- Group [F03D 15/101](#) is incomplete pending reclassification of documents from groups [F03D 15/00](#), [F03D 15/10](#) and [F05B 2260/40311](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 15/15 . . {Changing or adjusting stroke}
- 15/20 . Gearless transmission, i.e. direct-drive
- 15/201 . {using friction drives, e.g. belts}

WARNING

Group [F03D 15/201](#) is incomplete pending reclassification of documents from groups [F03D 15/00](#), [F05B 2260/402](#), [F05B 2260/4021](#), [F05B 2260/4022](#) and [F05B 2260/4023](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 15/202 . {using hydraulic transmission}

WARNING

Group [F03D 15/202](#) is incomplete pending reclassification of documents from groups [F03D 15/00](#) and [F05B 2260/406](#).

Groups [F03D 15/00](#), [F05B 2260/406](#) and [F03D 15/202](#) should be considered in order to perform a complete search.

- 15/205 . {to the generator located at the tower bottom}

WARNING

Group [F03D 15/205](#) is incomplete pending reclassification of documents from groups [F03D 9/25](#) and [F03D 15/00](#).

Groups [F03D 9/25](#), [F03D 15/00](#) and [F03D 15/205](#) should be considered in order to perform a complete search.

- 15/207 . {to multiple generators, e.g. in series}

WARNING

Group [F03D 15/207](#) is incomplete pending reclassification of documents from groups [F03D 9/25](#) and [F03D 15/00](#).

Groups [F03D 9/25](#), [F03D 15/00](#) and [F03D 15/207](#) should be considered in order to perform a complete search.

- 17/00 **Monitoring or testing of wind motors, e.g. diagnostics (testing during commissioning of wind motors [F03D 13/30](#))**

WARNING

Group [F03D 17/00](#) is impacted by reclassification into groups [F03D 17/001](#), [F03D 17/002](#), [F03D 17/003](#), [F03D 17/004](#), [F03D 17/005](#), [F03D 17/006](#), [F03D 17/0065](#), [F03D 17/007](#), [F03D 17/008](#), [F03D 17/009](#), [F03D 17/011](#), [F03D 17/012](#), [F03D 17/013](#), [F03D 17/014](#), [F03D 17/015](#), [F03D 17/016](#), [F03D 17/017](#), [F03D 17/018](#), [F03D 17/021](#), [F03D 17/022](#), [F03D 17/024](#), [F03D 17/025](#), [F03D 17/026](#), [F03D 17/027](#), [F03D 17/028](#), [F03D 17/0285](#), [F03D 17/029](#), [F03D 17/031](#), [F03D 17/032](#), [F03D 17/033](#), [F03D 17/034](#) and [F03D 17/036](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 17/001 . {Inspection}

WARNING

Groups [F03D 17/001](#) and [F03D 17/004](#) are incomplete pending reclassification of documents from groups [F03D 17/00](#), [F03D 80/50](#), [F05B 2260/80](#) and [F05B 2260/83](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 17/002 . . {by testing or performing a safety check}

WARNING

Group [F03D 17/002](#) is incomplete pending reclassification of documents from groups [F03D 17/00](#), [F03D 80/50](#) and [F05B 2260/83](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 17/003 . . {characterised by using optical devices, e.g. lidar or cameras}

WARNING

Group [F03D 17/003](#) is incomplete pending reclassification of documents from groups [F03D 17/00](#), [F03D 80/50](#), [F05B 2260/83](#), [F05B 2270/804](#), [F05B 2270/8041](#) and [F05B 2270/8042](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 17/004 . . {by using remote inspection vehicles, e.g. robots or drones}

17/005	<ul style="list-style-type: none"> • {using computation methods, e.g. neural networks} <p>WARNING</p> <p>Groups F03D 17/005, F03D 17/006 and F03D 17/0065 are incomplete pending reclassification of documents from groups F03D 17/00, F05B 2260/80, F05B 2260/82, F05B 2260/821, F05B 2260/8211 and F05B 2260/84.</p> <p>All groups listed in this Warning should be considered in order to perform a complete search.</p>	17/012	<ul style="list-style-type: none"> • • {for monitoring wear or clearance} <p>WARNING</p> <p>Group F03D 17/012 is incomplete pending reclassification of documents from group F03D 17/00.</p> <p>Groups F03D 17/00 and F03D 17/012 should be considered in order to perform a complete search.</p>
17/006	<ul style="list-style-type: none"> • • {Estimation methods} 	17/013	<ul style="list-style-type: none"> • • {for detecting abnormalities or damage} <p>WARNING</p> <p>Group F03D 17/013 is incomplete pending reclassification of documents from group F03D 17/00.</p> <p>Groups F03D 17/00 and F03D 17/013 should be considered in order to perform a complete search.</p>
17/0065	<ul style="list-style-type: none"> • • {for diagnostics} 	17/014	<ul style="list-style-type: none"> • • • {indicative of a fault or failure}
17/007	<ul style="list-style-type: none"> • {Wind farm monitoring} <p>WARNING</p> <p>Group F03D 17/007 is incomplete pending reclassification of documents from group F03D 17/00.</p> <p>Groups F03D 17/00 and F03D 17/007 should be considered in order to perform a complete search.</p>	17/015	<ul style="list-style-type: none"> • • {for monitoring vibrations} <p>WARNING</p> <p>Group F03D 17/015 is incomplete pending reclassification of documents from groups F03D 7/0296, F03D 17/00, F05B 2260/80 and F05B 2270/334.</p> <p>All groups listed in this Warning should be considered in order to perform a complete search.</p>
17/008	<ul style="list-style-type: none"> • • {through wake analysis} <p>WARNING</p> <p>Group F03D 17/008 is incomplete pending reclassification of documents from groups F03D 17/00 and F05B 2270/204.</p> <p>Groups F03D 17/00, F05B 2270/204 and F03D 17/008 should be considered in order to perform a complete search.</p>	17/016	<ul style="list-style-type: none"> • • • {indicative of rotor imbalance} <p>WARNING</p> <p>Group F03D 17/016 is incomplete pending reclassification of documents from groups F03D 7/0296 and F03D 17/00.</p> <p>Groups F03D 7/0296, F03D 17/00 and F03D 17/016 should be considered in order to perform a complete search.</p>
17/009	<ul style="list-style-type: none"> • {characterised by the purpose} <p>WARNING</p> <p>Groups F03D 17/009 and F03D 17/014 are incomplete pending reclassification of documents from groups F03D 17/00 and F05B 2260/80.</p> <p>All groups listed in this Warning should be considered in order to perform a complete search.</p>	17/017	<ul style="list-style-type: none"> • • • {Natural frequencies or oscillations} <p>WARNING</p> <p>Group F03D 17/017 is incomplete pending reclassification of documents from groups F03D 7/0296 and F03D 17/00.</p> <p>Groups F03D 7/0296, F03D 17/00 and F03D 17/017 should be considered in order to perform a complete search.</p>
17/011	<ul style="list-style-type: none"> • • {for monitoring mechanical loads or assessing fatigue; for monitoring structural integrity} <p>WARNING</p> <p>Group F03D 17/011 is incomplete pending reclassification of documents from groups F03D 17/00, F05B 2260/80, F05B 2270/331 and F05B 2270/332.</p> <p>All groups listed in this Warning should be considered in order to perform a complete search.</p>	17/018	<ul style="list-style-type: none"> • • {for monitoring temperature} <p>WARNING</p> <p>Group F03D 17/018 is incomplete pending reclassification of documents from groups F03D 17/00, F05B 2270/303 and F05B 2270/3032.</p> <p>All groups listed in this Warning should be considered in order to perform a complete search.</p>

17/021 . . {for monitoring power or current}

WARNING

Group [F03D 17/021](#) is incomplete pending reclassification of documents from group [F03D 17/00](#).

Groups [F03D 17/00](#) and [F03D 17/021](#) should be considered in order to perform a complete search.

17/022 . . {for monitoring displacement}

WARNING

Group [F03D 17/022](#) is incomplete pending reclassification of documents from groups [F03D 17/00](#) and [F05B 2270/821](#).

Groups [F03D 17/00](#), [F05B 2270/821](#) and [F03D 17/022](#) should be considered in order to perform a complete search.

17/024 . . {for monitoring sound or acoustic signals}

WARNING

Group [F03D 17/024](#) is incomplete pending reclassification of documents from groups [F03D 17/00](#), [F05B 2270/333](#) and [F05B 2270/81](#).

All groups listed in this Warning should be considered in order to perform a complete search.

17/025 . . {for calibrating}

WARNING

Group [F03D 17/025](#) is incomplete pending reclassification of documents from groups [F03D 17/00](#) and [F05B 2270/802](#).

Groups [F03D 17/00](#), [F05B 2270/802](#) and [F03D 17/025](#) should be considered in order to perform a complete search.

17/026 . . {for assessing power production capabilities}

WARNING

Group [F03D 17/026](#) is incomplete pending reclassification of documents from group [F03D 17/00](#).

Groups [F03D 17/00](#) and [F03D 17/026](#) should be considered in order to perform a complete search.

17/027 . {characterised by the component being monitored or tested}

WARNING

Group [F03D 17/027](#) is incomplete pending reclassification of documents from groups [F03D 17/00](#) and [F05B 2260/80](#).

Groups [F03D 17/00](#), [F05B 2260/80](#) and [F03D 17/027](#) should be considered in order to perform a complete search.

17/028 . . {Blades}

WARNING

Group [F03D 17/028](#) is incomplete pending reclassification of documents from groups [F03D 17/00](#), [F05B 2260/80](#), [F05B 2270/17](#), [F05B 2270/33](#), [F05B 2270/332](#), [F05B 2270/333](#) and [F05B 2270/334](#).

All groups listed in this Warning should be considered in order to perform a complete search.

17/0285 . . . {Surfaces thereof}

WARNING

Group [F03D 17/0285](#) is incomplete pending reclassification of documents from groups [F03D 17/00](#), [F05B 2270/332](#), [F05B 2270/333](#) and [F05B 2270/334](#).

All groups listed in this Warning should be considered in order to perform a complete search.

17/029 . . {Blade pitch or yaw drive systems, e.g. pitch or yaw angle}

WARNING

Group [F03D 17/029](#) is incomplete pending reclassification of documents from groups [F03D 7/0224](#), [F03D 17/00](#), [F05B 2270/328](#), [F05B 2270/329](#), [F05B 2270/332](#), [F05B 2270/333](#) and [F05B 2270/334](#).

All groups listed in this Warning should be considered in order to perform a complete search.

17/031 . . {Shafts}

WARNING

Group [F03D 17/031](#) is incomplete pending reclassification of documents from groups [F03D 17/00](#), [F05B 2270/332](#), [F05B 2270/333](#) and [F05B 2270/334](#).

All groups listed in this Warning should be considered in order to perform a complete search.

17/032 . . {Bearings}

WARNING

Group [F03D 17/032](#) is incomplete pending reclassification of documents from groups [F03D 17/00](#), [F05B 2260/80](#), [F05B 2270/332](#), [F05B 2270/333](#) and [F05B 2270/334](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 17/033 . . {Gearboxes}

WARNING

Group [F03D 17/033](#) is incomplete pending reclassification of documents from groups [F03D 17/00](#), [F05B 2270/332](#), [F05B 2270/333](#) and [F05B 2270/334](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 17/034 . . {Towers}

WARNING

Group [F03D 17/034](#) is incomplete pending reclassification of documents from groups [F03D 17/00](#), [F05B 2260/80](#), [F05B 2270/17](#), [F05B 2270/33](#), [F05B 2270/332](#), [F05B 2270/333](#) and [F05B 2270/334](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 17/036 . . {Generators}

WARNING

Group [F03D 17/036](#) is incomplete pending reclassification of documents from groups [F03D 17/00](#), [F05B 2260/80](#), [F05B 2270/3032](#), [F05B 2270/332](#), [F05B 2270/333](#) and [F05B 2270/334](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 80/00 **Details, components or accessories not provided for in groups [F03D 1/00](#) - [F03D 17/00](#)**

WARNING

Group [F03D 80/00](#) is impacted by reclassification into groups [F03D 13/2005](#), [F03D 13/201](#), [F03D 13/202](#), [F03D 13/203](#), [F03D 13/204](#), [F03D 13/205](#), [F03D 13/206](#), [F03D 80/001](#), [F03D 80/002](#), [F03D 80/003](#), [F03D 80/004](#), [F03D 80/005](#) and [F03D 80/011](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 80/001 . {Human safety arrangements, e.g. evacuation or emergency}

WARNING

Group [F03D 80/001](#) is incomplete pending reclassification of documents from groups [F03D 80/00](#) and [F03D 80/50](#).

Groups [F03D 80/00](#), [F03D 80/50](#) and [F03D 80/001](#) should be considered in order to perform a complete search.

- 80/002 . {Micro-siting, i.e. process through which the specific location or arrangement of wind turbine is determined}

WARNING

Group [F03D 80/002](#) is incomplete pending reclassification of documents from groups [F03D 13/30](#), [F03D 80/00](#), [F05B 2270/20](#) and [F05B 2270/204](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 80/003 . {Power-supply to auxiliary components, e.g. to pitch drives or cooling fans}

WARNING

Group [F03D 80/003](#) is incomplete pending reclassification of documents from groups [F03D 80/00](#), [F03D 80/82](#), [F03D 80/85](#), [F05B 2270/502](#), [F05B 2270/504](#), [F05B 2270/506](#) and [F05B 2270/508](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 80/004 . {for reducing adverse effects on animals, e.g. preventing avian collisions; Detection of animals}

WARNING

Group [F03D 80/004](#) is incomplete pending reclassification of documents from groups [F03D 80/00](#) and [F03D 80/10](#).

Groups [F03D 80/00](#), [F03D 80/10](#) and [F03D 80/004](#) should be considered in order to perform a complete search.

- 80/005 . {for reducing noise pollution}

WARNING

Group [F03D 80/005](#) is incomplete pending reclassification of documents from groups [F03D 80/00](#), [F05B 2260/96](#), [F05B 2260/962](#), [F05B 2260/964](#), [F05B 2260/966](#) and [F05B 2270/333](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 80/011 . {Decommissioning}

WARNING

Group [F03D 80/011](#) is incomplete pending reclassification of documents from groups [F03D 13/30](#), [F03D 80/00](#) and [F05B 2230/70](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 80/10 . Arrangements for warning air traffic
WARNING
 Group [F03D 80/10](#) is impacted by reclassification into group [F03D 80/004](#).
 Groups [F03D 80/10](#) and [F03D 80/004](#) should be considered in order to perform a complete search.
- 80/20 . Arrangements for avoiding shadow flicker
 80/30 . Lightning protection
WARNING
 Group [F03D 80/30](#) is impacted by reclassification into group [F03D 80/301](#).
 Groups [F03D 80/30](#) and [F03D 80/301](#) should be considered in order to perform a complete search.
- 80/301 . . {Lightning receptor and down conductor systems in or on blades}
WARNING
 Group [F03D 80/301](#) is incomplete pending reclassification of documents from groups [F03D 1/0675](#), [F03D 80/30](#) and [F05B 2240/85](#).
 All groups listed in this Warning should be considered in order to perform a complete search.
- 80/40 . Ice detection; De-icing means
WARNING
 Group [F03D 80/40](#) is impacted by reclassification into groups [F03D 80/401](#), [F03D 80/402](#), [F03D 80/403](#) and [F03D 80/405](#).
 All groups listed in this Warning should be considered in order to perform a complete search.
- 80/401 . . {De-icing by electrical resistance heating}
WARNING
 Group [F03D 80/401](#) is incomplete pending reclassification of documents from group [F03D 80/40](#).
 Groups [F03D 80/40](#) and [F03D 80/401](#) should be considered in order to perform a complete search.
- 80/402 . . {De-icing by convective heating}
WARNING
 Group [F03D 80/402](#) is incomplete pending reclassification of documents from group [F03D 80/40](#).
 Groups [F03D 80/40](#) and [F03D 80/402](#) should be considered in order to perform a complete search.
- 80/403 . . {Inducing vibrations for de-icing; De-icing by shaking}
WARNING
 Group [F03D 80/403](#) is incomplete pending reclassification of documents from group [F03D 80/40](#).
 Groups [F03D 80/40](#) and [F03D 80/403](#) should be considered in order to perform a complete search.
- 80/405 . . {Ice detection}
WARNING
 Group [F03D 80/405](#) is incomplete pending reclassification of documents from group [F03D 80/40](#).
 Groups [F03D 80/40](#) and [F03D 80/405](#) should be considered in order to perform a complete search.
- 80/50 . Maintenance or repair
WARNING
 Group [F03D 80/50](#) is impacted by reclassification into groups [F03D 17/001](#), [F03D 17/002](#), [F03D 17/003](#), [F03D 17/004](#), [F03D 80/001](#), [F03D 80/501](#), [F03D 80/502](#), [F03D 80/504](#), [F03D 80/505](#), [F03D 80/507](#) and [F03D 80/509](#).
 All groups listed in this Warning should be considered in order to perform a complete search.
- 80/501 . . {by using platforms}
WARNING
 Group [F03D 80/501](#) is incomplete pending reclassification of documents from groups [F03D 80/50](#), [F03D 80/55](#) and [F05B 2230/80](#).
 All groups listed in this Warning should be considered in order to perform a complete search.
- 80/502 . . {of rotors or blades}
WARNING
 Group [F03D 80/502](#) is incomplete pending reclassification of documents from groups [F03D 80/50](#) and [F05B 2230/80](#).
 Groups [F03D 80/50](#), [F05B 2230/80](#) and [F03D 80/502](#) should be considered in order to perform a complete search.
- 80/504 . . {of powertrains, e.g. main shafts or generators}
WARNING
 Group [F03D 80/504](#) is incomplete pending reclassification of documents from groups [F03D 80/50](#) and [F05B 2230/80](#).
 Groups [F03D 80/50](#), [F05B 2230/80](#) and [F03D 80/504](#) should be considered in order to perform a complete search.

- 80/505 . . {Locking rotors in position}

WARNING

Group [F03D 80/505](#) is incomplete pending reclassification of documents from groups [F03D 80/50](#), [F05B 2230/80](#) and [F05B 2260/31](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 80/507 . . {Retrofitting; Repurposing, i.e. reusing of wind motor parts for different purposes; Upgrading, i.e. replacing parts for improving the wind turbine performance}

WARNING

Group [F03D 80/507](#) is incomplete pending reclassification of documents from groups [F03D 80/50](#) and [F05B 2230/80](#).

Groups [F03D 80/50](#), [F05B 2230/80](#) and [F03D 80/507](#) should be considered in order to perform a complete search.

- 80/509 . . {Maintenance scheduling}

WARNING

Group [F03D 80/509](#) is incomplete pending reclassification of documents from groups [F03D 80/50](#) and [F05B 2230/80](#).

Groups [F03D 80/50](#), [F05B 2230/80](#) and [F03D 80/509](#) should be considered in order to perform a complete search.

- 80/55 . . Cleaning ([F03D 80/40](#) takes precedence)

WARNING

Group [F03D 80/55](#) is impacted by reclassification into group [F03D 80/501](#).

Groups [F03D 80/55](#) and [F03D 80/501](#) should be considered in order to perform a complete search.

- 80/60 . . Cooling or heating of wind motors

WARNING

Group [F03D 80/60](#) is impacted by reclassification into groups [F03D 80/601](#) and [F03D 80/602](#).

Groups [F03D 80/60](#), [F03D 80/601](#) and [F03D 80/602](#) should be considered in order to perform a complete search.

- 80/601 . . {using ambient airflow; Convective cooling of components}

WARNING

Group [F03D 80/601](#) is incomplete pending reclassification of documents from groups [F03D 80/60](#), [F05B 2240/14](#), [F05B 2260/20](#), [F05B 2260/221](#), [F05B 2260/222](#), [F05B 2260/224](#) and [F05B 2260/2241](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 80/602 . . {Heat transfer circuits; Refrigeration circuits}

WARNING

Group [F03D 80/602](#) is incomplete pending reclassification of documents from groups [F03D 80/60](#), [F05B 2240/14](#), [F05B 2260/20](#), [F05B 2260/205](#), [F05B 2260/207](#), [F05B 2260/221](#), [F05B 2260/222](#), [F05B 2260/224](#) and [F05B 2260/2241](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 80/70 . . Bearing or lubricating arrangements

WARNING

Group [F03D 80/70](#) is impacted by reclassification into groups [F03D 80/701](#), [F03D 80/703](#), [F03D 80/705](#), [F03D 80/707](#) and [F03D 80/709](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 80/701 . . {Pitch or yaw bearings}

WARNING

Group [F03D 80/701](#) is incomplete pending reclassification of documents from groups [F03D 7/0224](#), [F03D 15/10](#), [F03D 80/70](#), [F05B 2240/50](#), [F05B 2240/51](#), [F05B 2240/511](#), [F05B 2240/515](#), [F05B 2240/52](#), [F05B 2240/53](#), [F05B 2240/54](#) and [F05B 2260/79](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 80/703 . . {Shaft bearings}

WARNING

Group [F03D 80/703](#) is incomplete pending reclassification of documents from groups [F03D 15/10](#), [F03D 80/70](#), [F05B 2240/50](#), [F05B 2240/51](#), [F05B 2240/511](#), [F05B 2240/515](#), [F05B 2240/52](#), [F05B 2240/53](#) and [F05B 2240/54](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 80/705 . . {Lubrication circuits; Lubrication delivery means}

WARNING

Groups [F03D 80/705](#), [F03D 80/707](#) and [F03D 80/709](#) are incomplete pending reclassification of documents from groups [F03D 15/10](#), [F03D 80/70](#) and [F05B 2260/98](#).

All groups listed in this Warning should be considered in order to perform a complete search.

- 80/707 . . . {Gearing lubrication, e.g. gear boxes}

- 80/709 . . . {Bearing lubrication}

- 80/80 . . Arrangement of components within nacelles or towers

F03D

80/82 . . {of electrical components}

WARNING

Group [F03D 80/82](#) is impacted by reclassification into groups [F03D 80/003](#) and [F03D 80/821](#).

Groups [F03D 80/82](#), [F03D 80/003](#) and [F03D 80/821](#) should be considered in order to perform a complete search.

80/821 . . . {within nacelles}

WARNING

Group [F03D 80/821](#) is incomplete pending reclassification of documents from groups [F03D 80/82](#) and [F03D 80/85](#).

Groups [F03D 80/82](#), [F03D 80/85](#) and [F03D 80/821](#) should be considered in order to perform a complete search.

80/85 . . . {Cabling}

WARNING

Group [F03D 80/85](#) is impacted by reclassification into groups [F03D 80/003](#) and [F03D 80/821](#).

Groups [F03D 80/85](#), [F03D 80/003](#) and [F03D 80/821](#) should be considered in order to perform a complete search.

80/88 . . {of mechanical components}

WARNING

Group [F03D 80/88](#) is impacted by reclassification into group [F03D 80/881](#).

Groups [F03D 80/88](#) and [F03D 80/881](#) should be considered in order to perform a complete search.

80/881 . . . {within nacelles}

WARNING

Group [F03D 80/881](#) is incomplete pending reclassification of documents from group [F03D 80/88](#).

Groups [F03D 80/88](#) and [F03D 80/881](#) should be considered in order to perform a complete search.